

---

# Welding

- *1910 Subpart Q*
- *1926 Subpart J*

**Presented by:** Steve Davis, GRM

---



ETTA, OSH Division, (919) 807-2875



中行

# Welding

---

***You Must Understand the Types of Welding  
You May See in General Industry or  
Construction. What are three types?***


1. \_\_\_\_\_
2. \_\_\_\_\_
3. \_\_\_\_\_

***Are the Hazards All the Same?***

# What Type of Welding is This?



# What Type of Welding is This?



# What Type of Welding/Cutting is This?



# What Type of Welding is This?



# What Type of Welding is This?







# 1910 Subpart Q

---

- ✓ **1910.251 – Definitions**
- ✓ **1910.252 - General Requirements**
- ✓ **1910.253 - Oxygen-fuel gas welding & cutting**
- ✓ **1910.254 - Arc welding and cutting**
- ✓ **1910.255 - Resistance welding**

# 1926 Subpart J

---

- ✓ **1926.350 – Gas Welding & Cutting**
- ✓ **1926.351 – Arc Welding & Cutting**
- ✓ **1926.352 – Fire Prevention**
- ✓ **1926.353 – Ventilation & Protection in Welding, Cutting & Heating**
- ✓ **1926.354 – Welding, Cutting & Heating in Preserved Coatings**

# Incorporated by reference

---

- ✓ ANSI Standards
- ✓ Compressed Gas Association Standards



# Other Related OSHA Standards

---

- ✓ 1910.102 - Acetylene
- ✓ 1910.104 - Oxygen
- ✓ 1926.350 - Gas welding and cutting
- ✓ 1926.351 - Arc welding and cutting
- ✓ 1926.352 - Fire prevention
- ✓ 1926.353 - Ventilation and protection in welding, cutting, and heating
- ✓ 1926.354 - Welding, cutting, and heating in way of preservative coatings

---

# Most Frequently Cited - 2009

---

- ✓ 1910.253(b)(4)(iii) Oxygen cylinder storage  
1926.350(a)(10) Separation: Distance
- ✓ 1910.253(b)(2)(ii) Cylinder storage – Inside of buildings
- ✓ 1910.252(b)(2)(iii) Protection from rays  
1926.353(d)(1)(iii) Protection from ultraviolet rays
- ✓ 1910.254(d)(9)(iii) Arc welding/cutting – damaged cables
- ✓ 1926.351(b)(2) Maintenance of cables

# Most Frequently Cited - 2009

---

- ✓ 1910.253(b)(2)(iv) Valve caps  
1926.350(a)(1) Valve protection caps
- ✓ 1926.350(h) Regulators/gauges in working order
- ✓ 1926.352(d) Fire extinguishing equipment in area

# Welding Terminology

---

## Arc welding

- Carbon Arc Welding CAW
- Gas Metal Arc Welding GMAW
- Gas Tungsten Arc Welding GTAW
- Plasma Arc Welding PAW
- Shielded Metal Arc Welding SMAW
- Stud Arc Welding SW
- Submerged Arc Welding SAW

# Welding Terminology

# Oxyfuel Gas Welding

- Oxyacetylene Welding OAW
- Oxyhydrogen Welding OHW
- Pressure Gas Welding PGW

# Welding Terminology

---

## Brazing


- Diffusion Brazing DFB
- Dip Brazing DB
- Furnace Brazing FB
- Induction Brazing IB
- Infrared Brazing IRB
- Resistance Brazing RB
- Torch Brazing TB

# Welding Terminology Slang

---

- Stick
- MIG
- TIG
- Sub Arc
- Gouging
- Plasma Cutting
- Torch Cutting



# Welding Call Outs



# Welding – Types & Typical Symbols

---


- **FILLET** – Type of weld, approximately triangular cross section joining two surfaces at approximately exact angles to each other.
- **SEAM** – A type of welding, continuous weld made between or upon overlapping metal parts.




# Welding – Types & Typical Symbols

---

- **BEVEL** – A type of groove weld in which one member has a joint edge beveled from one side



- **V-Groove** – A groove weld in which the joint edge of each member is beveled from the similar side.



# AISC Welding – Best Practices

---


- Certified Welders (Weld Certs)
- Welding Procedures (WPS)
- Setting up the Welding Machine Properly
- Use of Amp Meter
- Weld Electrode (Rod) Storage in Rod Oven
- Weld Gauges (to visually Inspect the Weld)
- Weld Inspections by Qualified Persons

# AISC Weld Procedures



Williams Erection Company  
Welding Procedure Specification  
Bu 4a GF NR 212

Page 1 of 2

WPS No. <u>Bu 4a GF NR 212</u>	Date <u>5/8/2000</u>	By <u>Philip Torchio</u>	Type <u>Manual</u> <input type="checkbox"/> <u>Machine</u> <input type="checkbox"/>																								
Authorized By <u>P. Torchio</u>	Date <u>5/8/2000</u>	Revision <u>0</u>	Semi-Auto <input checked="" type="checkbox"/> Auto <input type="checkbox"/>																								
Welding Process(es) <u>FCAW</u>	Prequalified <input checked="" type="checkbox"/>																										
Supporting PQR(s)																											
<b>JOINT</b> Type <u>Butt</u> Backing Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Single Weld <input checked="" type="checkbox"/> Double Weld <input type="checkbox"/> Backing Material <u>A-36</u> Root Opening <u>as shown</u> Root Face Dimension <u>chisel point</u> Groove Angle <u>45</u> Radius (J-U) <u> </u> Back Gouge Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Method <u> </u>		 <table border="1"> <tr> <td>Joint Designation</td> <td>Base Metal Thickness (in.)</td> <td>Root Gap (in.)</td> <td>Root Bevel (in.)</td> <td>Root Face Dimension</td> <td>Penetration (in.)</td> <td>Welding Position</td> <td>Welding Procedure</td> </tr> <tr> <td>Single V-groove</td> <td>1/8 to 1/2</td> <td>0 to 1/8</td> <td>0 to 1/8</td> <td>Chisel point</td> <td>0 to 1/8</td> <td>A</td> <td> </td> </tr> <tr> <td>Single V-groove</td> <td>1/8 to 1/2</td> <td>0 to 1/8</td> <td>0 to 1/8</td> <td>Chisel point</td> <td>0 to 1/8</td> <td>A</td> <td> </td> </tr> </table>		Joint Designation	Base Metal Thickness (in.)	Root Gap (in.)	Root Bevel (in.)	Root Face Dimension	Penetration (in.)	Welding Position	Welding Procedure	Single V-groove	1/8 to 1/2	0 to 1/8	0 to 1/8	Chisel point	0 to 1/8	A		Single V-groove	1/8 to 1/2	0 to 1/8	0 to 1/8	Chisel point	0 to 1/8	A	
Joint Designation	Base Metal Thickness (in.)	Root Gap (in.)	Root Bevel (in.)	Root Face Dimension	Penetration (in.)	Welding Position	Welding Procedure																				
Single V-groove	1/8 to 1/2	0 to 1/8	0 to 1/8	Chisel point	0 to 1/8	A																					
Single V-groove	1/8 to 1/2	0 to 1/8	0 to 1/8	Chisel point	0 to 1/8	A																					
<b>BASE METALS</b> Material Spec. <u>ASTM A 572</u> to <u>GR 50</u> Type or Grade <u>Cat. B Tble 3.2</u> to <u> </u> Thickness: Groove (in.) <u>1/8</u> - <u>unlimited</u> Fillet ( ) <u> </u> Diameter (Pipe, ) <u> </u>		<b>POSITION</b> Position of Groove <u>All</u> Fillet <u>All</u> Vertical Progression: <input checked="" type="checkbox"/> Up <input type="checkbox"/> Down																									
<b>FILLER METALS</b> AWS Specification <u>A 5.20-79</u> <u>E 71 T G</u> AWS Classification <u>9</u> <u>Lincoln</u> <u>NR 212</u>		<b>ELECTRICAL CHARACTERISTICS</b> Transfer Mode (GMAW): <b>OK to weld in any position but if welding vertical you must go vertical up</b>																									
<b>SHIELDING</b> Flux <u>Gas NA</u> None <u>Composition</u> Electrode-Flux (Class) <u>Flow Rate</u> <u>NA</u> <u>Gas Cup Size</u>		<b>TECHNIQUE</b> Stringer or Weave Bead <u>Both</u> <b>Procedure is for</b> <u>side) Multiple</u> <b>E 71 T G welding</b> <u>al na</u> <b>Wire</b> <u>steral na</u> <b>Lincoln NR 212</b> <u>angle na</u>																									
<b>PREHEAT</b> Preheat Temp., Min. <u>32 Deg F</u> Thickness Up to 3/4" Temperature <u>32 Deg F</u> Over 3/4" to 1-1/2" <u>50 Deg F</u> Over 1-1/2" to 2-1/2" <u>150 Deg F</u> Over 2-1/2" <u>225 Deg F</u> Interpass Temp., Min. <u>p.heat spc</u> Max. <u> </u>		Contact Tube to Work Distance <u>1/2 to 1"</u> Peening <u>none</u> Interpass Cleaning <u>chip grind or gouge</u>																									
<b>POSTWELD HEAT TREATMENT</b> <u>PWHT Required</u> <input type="checkbox"/> Temp. <u> </u> Time <u> </u>		<b>WELDING PROCEDURE</b>																									
Layer/Pass	Process	Filler Metal Class	Diameter	Cur. Type	Amps or WFS	Volts	Travel Speed	Other Notes																			
1	FCAW	E 71-T G	.045	DCEN	90-115	15-17	70-90"	1/4>T>5/8																			
1	FCAW	E 71-T G	.045	DCEN	120-140	17-18	90-100"	1/2>T>3/4																			
1	FCAW	E 71-T G	5/64	DCEN	150-180	16-19	65-75"	1/2>T>3/4																			
1	FCAW	E 71-T G	5/64	DCEN	185-225	19-21	80-115"	1/2>T>1"																			
1	FCAW	E 71-T G	5/64	DCEN	230-275	20-21	80-115"	1/2>T>1"																			
1	FCAW	E 71-T G	5/64	DCEN	275-325	21-23	110-150"	T>3/4																			

# Fire Protection

---

- ✓ Remove fire hazards from the welding area
- ✓ If fire hazards cannot be removed then guards must be used
- ✓ Suitable fire extinguishers must be maintained in a state of readiness







# Fire Watch

---

- ✓ Required when a major fire hazard exists,
- ✓ Flammable materials within 35 feet
- ✓ Flammable materials more than 35 feet away could easily catch on fire
- ✓ Must continue for at least 30 minutes after welding work is finished

# Exercise

---

- Find in Subpart Q Where it Requires a Fire Watch to Remain in the Welding Area 30 Minutes AFTER the Welding has been Completed.

◆ **Answer: 29CFR 1910.252(a)(2)(iii)(B)**

DATE		LOCATION/BUILDING & FLOOR	PERMIT NO.
7/10/03		10th Floor	0020165
HOT WORK BEING DONE BY:		REQUIRED PRECAUTIONS CHECKLIST (Check all that apply)	
<input type="checkbox"/> Blue Ridge Paper Products, Inc. <input checked="" type="checkbox"/> Contractor: <i>Coast</i>		<b>FOR ALL WORK</b> -Requirements within 35 ft. <ul style="list-style-type: none"> <li><input type="checkbox"/> Flammable/combustible liquids, dust, lint, oily deposits removed</li> <li><input type="checkbox"/> Non-combustible floors swept clean</li> <li><input type="checkbox"/> Other combustibles removed or covered</li> <li><input type="checkbox"/> Cables, conveyor, covered or fire-resistant</li> <li><input type="checkbox"/> Vapors suspended below work</li> <li><input type="checkbox"/> Flammable/explosive atmosphere tested (LEL-0%) and eliminated if necessary</li> <li><input type="checkbox"/> Combustible floors wet down and covered</li> <li><input type="checkbox"/> All wall and floor openings protected</li> <li><input type="checkbox"/> Confined space is vented and/or respiratory protection applied</li> <li><input type="checkbox"/> Adjusting area/equipment protected from conduction/radiation of heat</li> </ul>	
<b>VERIFICATION OF PRECAUTIONS</b> I verify that the necessary precautions have been identified and that the location where the work will be done has been examined to ensure the precautions have been taken.		<b>FOR WORK ON WALLS OR CEILING</b> <ul style="list-style-type: none"> <li><input type="checkbox"/> Construction is non-combustible and without combustible covering or insulation</li> <li><input type="checkbox"/> Combustibles on other side of walls/ceilings moved</li> </ul>	
<b>SIGNATURE</b> <i>Contractor Safety Supervisor</i>		<b>DATE</b> <i>6/10/03</i>	
<b>Production Safety Supervisor</b> <i>Contractor Safety Supervisor</i>		<b>DATE</b> <i>6/10/03</i>	
<b>Final Verification/Authorization</b> <ul style="list-style-type: none"> <li><input type="checkbox"/> Automatic Fire Protection Systems are in service</li> <li><input type="checkbox"/> Pressures are correct and verification section is complete</li> </ul>		<b>FOR WORK ON ENCLOSED EQUIPMENT/TANKS/PIPING/DUCTS</b> <ul style="list-style-type: none"> <li><input type="checkbox"/> Combustibles removed/flammable liquids and vapors purged</li> <li><input type="checkbox"/> Proper lock-out applied</li> </ul>	
<b>Signed:</b> <i>Contractor Safety Supervisor</i>		<b>FIRE WATCH</b> <ul style="list-style-type: none"> <li><input type="checkbox"/> Required, Number _____</li> <li><input type="checkbox"/> Supplied with suitable Fire Extinguisher</li> <li><input type="checkbox"/> Required and trained in its use</li> <li><input type="checkbox"/> Will be provided during and for 30 minutes after work, including coffee/lunch breaks</li> <li><input type="checkbox"/> Supplied with charged fire-extinguisher water hose and trained in its use.</li> </ul>	
<b>Fire Safety Supervisor</b> <b>PERMIT HOLDER:</b> <i>Coast</i>		<b>MAINTENANCE</b> <i>No N/A</i>	
<b>Fire Watch Signoff:</b> The work area and all adjacent areas to which sparks or heat might have spread were inspected during the fire watch period and were found fire safe.			
<b>Final Checkup:</b> The work area was monitored for 4 hours following HOT WORK and found fire safe.		<b>DATE:</b> <i>6/10/03</i>	
		<b>TIME:</b> <i>10:00 AM</i>	



DIGESTER CAP  
BE ON PRIOR  
LOAD/COOK SW  
BEING TURNED TO

# Fire Prevention & Protection

---

Cutting or welding is not permitted in:

- ✓ Areas not authorized by management
- ✓ Sprinkled buildings when protection is impaired
- ✓ The presence of explosive atmospheres

# Welding & Cutting Containers

---

- ✓ Cleaned thoroughly of flammable materials such as greases, tars, acids, or
- ✓ Connections to the container must be disconnected or blanked

# Fall & Trip Hazards

---

- ✓ Welders exposed to falls must be protected by use of guardrails or fall protection equipment
- ✓ Keep welding cable clear of passageways, ladders, and stairways



**Is This What You See in Your Plant?**

# Eye Protection

---

- ✓ Helmets or **hand** shields must be used during all arc welding & cutting operations, excluding submerged arc welding
- ✓ Attendants must also be provided with proper eye protection

# Eye Protection, cont.

---

- ✓ Goggles or other suitable eye protection must be used during all gas welding operations
- ✓ Spectacles without side shields, with suitable filter lenses are permitted for use during gas welding operations on light work, for torch brazing or for inspection









# Eye Protection, cont.

---

<u>Welding Operation</u>	<u>Shade No.</u>
Shielded metal-arc welding	10
Gas-shielded arc welding (nonferrous)	11
Gas-shielded arc welding (ferrous)	12
Soldering	2
Torch brazing	3 or 4
Heavy cutting, 6 inches and over	5 or 6

# Protection from Rays

---

- 1910.252(c)(1)(ii) Screens in General Industry
- 1926.351(e) Shielding. Whenever practicable, all arc welding and cutting operations shall be shielded by noncombustible or flameproof screens which will protect employees and other persons working in the vicinity from the direct rays of the arc.

# Protection from Rays - The Real Story

- Welding Flash Hazard is Within 35 ft. Boundary
- [www.twi.uk](http://www.twi.uk): 10 meters
- U.S. Army Health & Hygiene
- AWS Table
- Outside of 35 ft. No Significant Hazard Is Present

Arc Welding/Cutting Process	Base Metal	Shielding Gas	Arc Current in Amperes	Distance in m for 1 min	Distance in m for 10 min	Distance in m for 8 h
Shielded Metal Arc (Stick) GMAW	Mild steel	None	100-200	3.2	10	71
	Mild steel	CO <sub>2</sub>	90	0.95	3.0	21
			200	2.2	7.0	48
			350	4.0	13	87
	Mild steel	CO <sub>2</sub>	175	1.1	3.6	25
			350	2.3	7.3	51
		95% Ar + 5% O <sub>2</sub>	150	2.9	9.3	65
			350	6.7	21	150
		Ar	150	3.2	10	70
GTAW	Mild steel	Ar	300	5.0	16	110
		He	150	1.6	5.0	34
			300	3.2	10	69
	Mild steel	Ar	50	0.32	1.0	6.9
			150	0.90	2.8	20
	Al	He	300	1.7	5.5	38
		Ar	250	3.0	9.5	66
			50 AC	0.32	1.0	6.9
PAW	Mild steel	He	150 AC	0.85	2.7	19
		Ar	250 AC	1.6	5.0	35
	Al	He	150 AC	0.94	3.0	21
		Ar	200-260	1.5	4.9	34
	85% Ar + 15% H <sub>2</sub>	He	100	3.0	9.4	65
		Ar	100-275	1.7	5.5	38
			400	1.4	4.4	31
PAC (dry)	Mild steel	65% Ar + 35% H <sub>2</sub>	1000	2.4	7.5	52
	Mild steel	N <sub>2</sub>	300	3.3	10	72
PAC (H <sub>2</sub> O)	Mild steel	N <sub>2</sub>	750	1.7	5.5	38

(a) These distances are approximate. To convert to feet, multiply the distance in meters by 3.3.

(b) The distances are based upon the worst-case exposure conditions: maximum UVR for exposure angle, arc gap, and electrode diameter.

(c) Invisible actinic UVR poses a potential hazard to cornea (called welder's flash) and skin (much like sunburn) and exposure is cumulative with each exposure over an 8-h workday per 24-h period.

(d) UVR is an abbreviation of the term UVA, Cincinnati, Ohio.

(e) These distances were based upon data from Lyon, T. L. et al, 1976. *Evaluation of the Potential Hazards for Actinic Ultraviolet Radiation Generated by Electric Welding and Cutting Arcs*. U.S. Army Environmental Hygiene Agency.

## Exposure Effects

Since the beginning of arc welding, welders have known welding and cutting operations can cause acute effects such as severe "sunburn" (erythema) of the skin and painful "welder's flash" (photokeratitis) of the cornea of the eye. Consequently, early welders empirically selected protective clothing and eyewear for comfortable viewing. Also, the U.S. Army adopted a measure to prevent eye injuries in industrial areas. Ordinary safety glasses were prescribed for all Army personnel, including welders and their helpers. As a by-product of physical injury prevention, the eyewear resulted in a dramatic drop in the incidence of welder's flash. Any stray invisible actinic UVR was also blocked by the transparent lenses.

## Exposure Limits

The first actinic UVR exposure guidelines were published by the American Conference of Governmental Industrial Hygienists (ACGIH) in 1972 (Ref. 1). These guidelines were intended to pre-

vent the acute effects of actinic UVR. The International Non-Ionizing Radiation Committee (INIRC) of the International Radiation Protection Association (IRPA) (Ref. 2) proposed similar guidelines in 1985. After considerable review, the International Commission on Non-Ionizing Radiation Protection (ICNIRP) (Ref. 3) revalidated and endorsed those limits. Besides being concerned about acute effects, these standards have also been shown to minimize any adverse effects and pose an extremely small risk for delayed effects.

## Instrumentation

By the early 1970s, several instruments were available to measure actinic UVR but many simpler instruments presented significant measurement errors primarily from a flaw called "stray light." The actinic UVR resulting in an acute injury followed a narrow range of wavelengths (from around 200-315 nm) with a varying "action spectrum" (peaking sharply at 270 nm). Producing an instrument with this wavelength response was difficult with known filters at that time. The better in-

struments were the traditional ultraviolet spectrometers that could manually scan UVR wavelengths, weigh the results against the exposure standard for each wavelength, then sum them for the net result.

## Joint Effort

In 1974, a joint effort was planned to determine the optical radiation hazards from electric arc welding and cutting operations. Testing was planned for six processes: gas tungsten arc welding (GTAW), gas metal arc welding (GMAW), flux cored arc welding (FCAW), plasma arc cutting (PAC), plasma arc welding (PAW), and shielded metal arc welding (SMAW). Organizations that provided personnel and equipment for the effort included Union Carbide Corp., the American Welding Society (AWS), Battelle Memorial Institute, National Institute of Occupational Safety and Health (NIOSH), and the U.S. Army Environmental Hygiene Agency (USAEEHA, now U.S. Army Center for Health Promotion and Preventive Medicine [USACHPPM]).

# Respirators

---

- ✓ When proper ventilation cannot be provided a respirator is required
- ✓ SCBA must be provided in IDLH Atmospheres

# WELD SAFELY

**AVOID BREATHING OR CONTACT  
WITH GASES & VAPORS**

**EXCESSIVE EXPOSURES HAVE BEEN KNOWN TO CAUSE:**

- Irritation & damage to skin, eyes, nose, throat & chest
- Metal fume fever
- Chronic heart & lung disease-pulmonary edema
- Asphyxiation in confined spaces
- Carbon monoxide poisoning



# Confined Spaces

---

- ✓ Gas cylinders and welding machines must be left outside of the space
- ✓ Heavy equipment mounted on wheels must be securely blocked to prevent movement
- ✓ The space must be ventilated with clean, breathable air by a mechanical system



# Confined Spaces

---

- ✓ Means of emergency retrieval must be provided
- ✓ An attendant with a pre-planned rescue procedure must be located outside the space
- ✓ The attendant must be trained in the hazards of confined spaces



# Confined Spaces

---

When arc welding is suspended for any substantial period of time:

- ✓ Electrodes must be removed from the holders
- ✓ Holders must be located so that accidental contact cannot occur
- ✓ The machine must be disconnected from the power source

# Confined spaces

---

When the torch will not be used for a substantial period of time:

- ✓ Valves must be closed & gas supply positively shut off at some point outside the confined area
- ✓ Where practicable, the torch and hose must also be removed from the confined space

# Oxygen-fuel gas welding

---

- ✓ Acetylene cannot be used at a pressure in excess of 15 psig or 30 psia
- ✓ The use of liquid acetylene is prohibited
- ✓ Only approved apparatus may be used

# Oxygen-fuel gas welding

---

- ✓ Portable cylinders used for the storage and shipment of compressed gases must be constructed in accordance with the regulations of the U.S. Department of Transportation, 49 CFR Parts 171-179.

---

✓ Acetylene  
Cylinders are filled  
with Calcium  
Silicate



# Oxygen-fuel gas welding

---

- ✓ Cylinders must be legibly marked to identifying their contents
- ✓ Markings must not be easily removed
- ✓ Whenever practical, the marking must be located on the shoulder of the cylinder

OXYGEN,  
COMPRESSED

UN 1072



OXYGEN

2

WARNING: SECURE ALL CLOSURES  
IN USE. WARNING: HEAT  
CAREFULLY ACCELERATES COMBUSTION  
AND CAN CAUSE AN EXPLOSION  
IF IN CONTACT WITH FLAMMABLE  
SUBSTANCES. COMPLY WITH  
ALL LOCAL, STATE AND FEDERAL  
REGULATIONS AND CODES.  
PROVIDED BY: NEALCO PRODUCTS  
1000 W. MICHIGAN AVE.

NEALCO PRODUCTS  
1000 W. MICHIGAN AVE.

# ACETYLENE

UN1001

**DANGER!** Flammable Gas. May Form  
Explosive Mixtures With Air.

KEEP AWAY FROM HEAT, FLAME AND SPARKS

**FLAMMABLE  
GAS**

DT30

Labelmaster, Chicago, IL

# Cylinder Storage

---

- ✓ Cylinders stored in buildings must be in a well-protected, well-ventilated, dry location
- ✓ Stored away from heat sources
- ✓ 20 feet from highly combustible materials
- ✓ Stored in assigned places away from elevators, stairs, or gangways.

# Cylinder Storage

---

- ✓ Storage space must be located where cylinders will not be damaged or tampered with
- ✓ Cylinders must not be kept in unventilated enclosures
- ✓ Empty cylinders must have their valves closed


# Cylinder Storage

---

- ✓ Oxygen and acetylene cylinders in storage must be separated by 20 feet or a 1/2 hour fire wall
- ✓ The cap must be in place except when cylinders are in use or connected for use

# Indoor Cylinder Storage

- Well protected
- Well insulated
- Dry
- Twenty feet from flammable or combustible materials



A large red arrow points from the fuel cylinder on the left to the oxygen cylinder on the right, indicating a distance of 20 feet between them. The word "20 Feet" is written in black text below the arrow.

20 Feet





13

# Cylinder Storage

---

- ✓ Cylinders in storage must be limited to a total gas capacity of 2,000 cubic feet or 300 pounds of liquefied petroleum gas
- ✓ Storage in excess of 2,000 cubic feet or 300 pounds must be in a separate room or kept outside
- ✓ Storage rooms or compartments must have no open flames and be well ventilated





FULL CYLINDERS



Is This Correct Storage of an Oxygen Cylinder?

# Oxygen-fuel gas welding

---

- ✓ Cylinders, valves, couplings, regulators, hose, and apparatus must be kept free from oily or greasy substances.
- ✓ Oxygen cylinders or apparatus must not be handled with oily hands or gloves.



# Transporting Cylinders

---

- ✓ When transporting cylinders by a crane, a cradle or suitable platform must be used
- ✓ Slings or electric magnets must not be used
- ✓ Valve-protection caps must always be in place
- ✓ Regulators must be removed
- ✓ Caps must not be used for lifting

# Transporting & Moving Cylinders


---

- ✓ Valve protection caps must be in place and secured.
- ✓ Hoist cylinders by cradle or pallet...not by choker, magnet or valve cap.
- ✓ Cylinders must be secured on truck, cart, or other device while in use & upright at all times.









LINCOLN  
ARC WELDER

# Oxygen-fuel gas welding

---

- ✓ Cylinder valves must be closed when work is finished
- ✓ Valves of empty cylinders must be closed

# Oxygen-fuel gas welding

---

- ✓ Cylinders must be kept away from welding operations so sparks or flames will not reach them, or shields must be used
- ✓ Cylinders must not be placed where they might become part of an electric circuit

# Oxygen-fuel gas welding

---

- ✓ Cylinders must be kept away from radiators, piping systems, layout tables, etc., that may be used for grounding electric circuits such as for arc welding machines
- ✓ Tapping an electrode against a cylinder to strike an arc is prohibited
- ✓ Cylinders must never be used as rollers or supports

# Oxygen-fuel gas welding

---

- ✓ Before connecting the regulator, the valve must be opened slightly for an instant and then closed
- ✓ Always stand to one side of the outlet when opening the cylinder valve
- ✓ Equipment must be installed and used in a manner approved by the manufacturer

# Protective Equipment, Hose & Regulators

---

Pressure relief devices:

- ✓ Service piping systems must be protected by pressure relief devices set to function at not more than the design pressure of the systems and discharging upwards to a safe location



# Oxygen-fuel Gas Welding

## Piping Protective Equipment


---

- ✓ Fuel-gas and oxygen piping systems must incorporate protective equipment
- ✓ Prevents backflow of oxygen into the fuel-gas supply system
- ✓ Prevents passage of a flash back into the fuel-gas supply system



# Flash Arrestors -The Real Story

- Flash Back Occurs at the Torch Head
- Flash Arrestors Should be Installed at the Torch Head
- Many New Torch Heads, (victor) have flash arrestors built in
- Mfg. State – Installation of another set of flash arrestors not recommended







# Oxygen-fuel gas welding

---

- ✓ Hose for oxy-fuel gas service must comply with the Specification for Rubber Welding Hose, 1958, Compressed Gas Association and Rubber Manufacturers Association
- ✓ When parallel lengths of oxygen and acetylene hose are taped together, not more than 4 inches out of 12 may be covered by tape

# Oxygen-fuel gas welding

---

- ✓ Hose connections must comply with the Standard Hose Connection Specifications, 1957, Compressed Gas Association
- ✓ Hose connections must be securely fastened to withstand twice the pressure to which they are normally subjected
- ✓ Hose showing leaks, burns, or other defects must be repaired or replaced

# Pressure-Reducing Regulators

---

- ✓ Pressure-reducing regulators must be used only for the gas and pressures for which they are intended.
- ✓ Regulators and gauges may only be repaired by skilled mechanics who have been trained to do so.

# Pressure-Reducing Regulators

---

- ✓ Gages on oxygen regulators must be marked "USE NO OIL"
- ✓ Connections on regulators must be inspected for leaks before use

# Arc Welding & Cutting

---


- ✓ Workers designated to operate arc welding equipment must be properly instructed and qualified
- ✓ Control apparatus must be enclosed except for the operating wheels, levers, or handles



# Arc Welding & Cutting

---

- ✓ Terminals for welding leads must be protected from accidental contact by personnel or metal objects
- ✓ Electrode holders must be placed so that they cannot make contact with persons or other objects









APNE







Good welding hood but  
inadequate skin protection

# Arc Welding & Cutting

---

- ✓ Cables with splices within 10 feet of the holder must not be used
- ✓ The welder should not coil or loop welding electrode cable around parts of his body





Damaged  
Lead





81 429

# Resistance Welding – Safety Controls

---

- ✓ Installation
- ✓ Thermal protection
- ✓ Personnel
- ✓ Guarding
- ✓ Spot and seam welding machines
- ✓ Voltage
- ✓ Capacitor welding
- ✓ Interlocks
- ✓ Guarding
- ✓ Shields
- ✓ Foot switches
- ✓ Stop buttons
- ✓ Safety pins
- ✓ Grounding

# Test

---

- What is the minimum storage distance between Oxygen and Acetylene Cylinders?
- Answer – 20 Ft. or  $\frac{1}{2}$  Hour Fire Wall 5 Ft. High
- What is the danger of oil on a Oxygen Cylinder Gauge?
- Answer - Fire or Explosion Danger
- How Long is a Fire Watch Required to Monitor the Work Area After the Welding Has Ended? Why?
- Answer - 30 Minutes, Metal Retains Heat!

---

# Test

---

- You Can Spice a Welding Lead within 5 ft of the Electrode Holder? True or False?
- False – No closer than 10 Ft.
- The Welder’s Helper Must Wear the Same Eye Protection as the Welder? True or False?
- Yes

What Can Happen When you  
DO IT WRONG!



# Thank You For Attending!

---

## Final Questions?

**1-800-NC-LABOR**

**(1-800-625-2267)**

**[www.nclabor.com](http://www.nclabor.com)**



# Handouts

---

Place all handouts at the end of this presentation