



United States  
CONSUMER PRODUCT SAFETY COMMISSION

---

---

## Elkay Recalls Water Coolers and Bottle Filling Stations Due to Shock Hazard



---

### Recall Summary

#### **Name of product:**

Elkay and Halsey Taylor water coolers and bottle filling stations

#### **Hazard:**

Internal screws that secure the grounding wire can break and allow the grounding wire to become loose, posing a shock hazard.

#### **Remedy:**

Repair

**Recall date:**

January 25, 2018

**Units:**

About 31,600

Consumer Contact:

**Elkay toll-free at 866-243-3070  
Monday through Friday from 7 a.m.  
to 4 p.m., email at  
Recall17@elkay.com or online at  
www.elkay.com and click on  
PRODUCT RECALL for more  
information. Consumers can also  
go to www.checkmycooler.com  
and enter a unit's full serial number  
to see if it is included in the recall.**

## Recall Details

### Description:

This recall involves Elkay and Halsey Taylor water coolers and bottle filling stations with the model numbers that begin with the letter and number combinations listed below. They are mainly installed in public facilities such as schools/universities, office buildings and airports. The brand Elkay or Halsey Taylor is identified on the front of the units with a nameplate or embossing and the affected serial numbers begin with the numbers 1704, 1705 or 1706. For more information on where to identify the model numbers and serial numbers on the units, visit [www.checkmycooler.com](http://www.checkmycooler.com) .

Elkay Models
ECP8, ECU8
EFA(4, 8, 14, 16, 20)
EFHA(8, 14)
EFOA8
EFY8
EHFSA8
EMABF(TL)8
ESWA8
EW(TL)A(4, 8, 14, 16, 20)
EWCA(4, 8, 14)
EZ (all models)

FD700(3, 5, 10)
HEW3
LFAE(8, 14, 20)
LFDE10
LMABF(TL)8
LVRC(TL)8
LVRCGRN(TL)8
LVRCHD(TL)8
LWAE(8, 14)
LWCE4
LZ (all models)
OHFAVR8
VRC(TL)8, VRC(TL)FR(D, 8)
VRCGRN(TL)8
VRCHD(TL)8

Halsey Taylor Models
HAC(G)8
HBW8
HOF14
HTHBHAC(G)8
HTHBHVR8

HTVZ (all models)
HVR(GRN)8
HVR8HD
S(300, 500, 10000)
SCWT(8, 14, 20)
SW(4, 8, 14)
WC8
WM(8, 14, 16)
XP8

Model Prefix	Elkay Product Photo
ECP8*	 A photograph of an Elkay ECP8 water cooler unit. The unit is a large, rectangular stainless steel tank with a black metal frame and a control panel on the right side. It has a black power cord and a black hose attached to the top. The tank is filled with water and has a black lid.

ECU8\*



EFA & LFAE\*

EFY8S1Z

EFHA\*

EFOA8\*



EHFSA8\*,

OHFAVR8S1Z



**EMABF\* & LMABF\***



**EMABF\*WS\* & LMABF\*WS\***



**ESWA8\***



EW(TL)A\*,  
LW(TL)A\*,  
EWCA\* and  
LWCE\*



EZ\* & LZ\*



EZS\*WS\* & LZS\*WS\*



FD700\*

LFDE\*



HEW3\*



<p>LVRC(GRN)* &amp; VRC(GRN)*</p>	
<p>LVRCHD8* &amp; VRCHD8*</p>	
<p>LVRCGRN*WS &amp; VRCGRN*WS*</p>	
<p>LVRC*WS* &amp; VRC*WS*</p>	

Model Prefix	Halsey Taylor Product Photo
HAC(G)8*	 Three smaller Halsey Taylor water cooler units, likely the HAC(G)8* models, shown from different angles. They are compact, rectangular units with a stainless steel finish and a built-in water dispensing spout.
HAC8EEBL*	 A larger Halsey Taylor water cooler unit, likely the HAC8EEBL* model. It features a built-in sink with a faucet and a separate water dispensing spout. The unit is a larger, more integrated design compared to the smaller models.

HBW8\*



HOF14\*,  
SCWT\*,  
XP8W\*



HTHB-HAC(8)\*



**HTHB-HVRGRN8\***



**HTHBHVR8\***



**HTVZ\***



**HVR(GRN)8\***



**HVR8HD\***



S-Series

S\*00\*



SW\*



WC8A\*



WM\*



### **Remedy:**

Consumers should immediately stop using the recalled water coolers and bottle filling stations, unplug the units and contact Elkay for a free repair.

### **Incidents/Injuries:**

The firm has received 362 reports of broken screws being found in units prior to installation. No injuries have been reported.

### **Sold At:**

Elkay distributors from May 2017 through June 2017 for between \$600 and \$7,450.

### **Manufacturer(s):**

Elkay Plumbing Products Company, of Savanna, Ill.

### **Distributor(s):**

Elkay Sales Inc., of Oak Brook, Ill.

**Manufactured In:**

U.S.

**Recall number:**

18-085

---