


Required Parts For Calibration of Air Velocity Meters with Probes or Attachments



Attachments and Probes must belong to Air Velocity Meter being tested



**Send all attachments and probes provided by Manufacturer.
Number and type of Attachments may vary.**

*It is highly recommended to send the Air Velocity Meter with all items to CTC in the Manufacturer's case to provide additional protection. Equipment should be packaged properly according to the :
Procedure for Packing Equipment to CTC.*