

# Gilibrator Pump Calibrators



*(Models may vary)*

*Power Adapter/Charger,  
Printer, And Pin Adapter,  
Are Not Required  
For Calibration &  
Should Not Be Sent*



Power Adapter/Charger



Printer



Pin Adapter



Due to their size Power Adapter/Chargers  
and Pin Adapters are easily lost.  
PLEASE DO NOT SEND AC  
Chargers or Pin Adapters to CTC.

*It is highly recommended to send  
Gilibrators to CTC in the  
Manufacturer's case to provide  
additional protection. Equipment  
should be packaged properly  
according to the :  
Procedure for Packing Equipment to CTC.*