


Required Parts For All Heat Stress Monitor Calibration

Sensors must belong
to Heat Stress Monitor
being tested

(Note: Some Makes and Models
may have Sensors permanently attached to the unit)



It is highly recommended to send Heat Stress Monitors to CTC in the Manufacturer's case to provide additional protection. Equipment should be packaged properly according to the :

Procedure for Packing Equipment to CTC.

http://intranet.osha.gov/dts/LAP/dts/ctc/packing_procedure.pdf

Sensors

(Note for shipping Heat Stress Monitors: Check all compartments to ensure probes are present, see pictures below - may vary by Make or Model)

