


Shipyard Employment

Electrical Machinery - Subpart L



- **Subpart L**
 - 1915.181 – Electrical circuits and distribution boards



Electrical Circuits and Distribution Boards

1915.181(b)

- Before work on electrical circuit, must be deenergized
 - Except when necessary for testing and adjustment



Electrical Circuits and Distribution Boards

1915.181(c)


- Open circuit breaker, open switch, or remove fuse
 - Tagged to indicate it is being worked on



Electrical Circuits and Distribution Boards

1915.181(d)

- Work performed immediately adjacent to an open front energized board or in back of energized board
 - Board covered or other equally safe means used to prevent contact with energized parts



Thank You For Attending!

Final Questions?

1-800-NC-LABOR
(1-800-625-2267)
www.nclabor.com



For Public Official's Use Only