

Required Parts For All Light Meter Calibration



**Sensor must belong
to Light Meter
being tested**

*(Note: Some Makes and Models
may have this item permanently attached to the unit)*



Sensor



When shipped it is highly recommended to keep Light Meters and Sensors together in the container being used. Equipment should be packaged properly according to the : Procedure for Packing Equipment to CTC.